

Checklist for warranties

AAAA

On the following pages you will find the most common reasons why a warranty is not granted. Be aware of the issues displayed in the next pages.

If the air spring, air strut, compressor or coil conversion kit does not have an Arnott sticker, it is never a warranty.



This list is not inclusive and does not guaranty that the rest will be granted as warranties. Warranties are determined by Arnott Europe.

Chinese products vs O.E.

You can recognize a Chinese product easily by looking at the color of the aluminum cans. The products usually look really new but are already broken.



NL +31 (0)73 7850 580 DE +49 (0)699 6759106 UK +44 (0)203 3186124 BE +32 (0)258 846 90



Air springs

Moving valve/Damaged Vos screw-thread

This is considered to be an installation error because the valve has been overtightened.





Bottom part of the air spring is broken

This is can be caused by an installation error when the air spring is not connected properly or by a broken/bad shock. The shock absorber no longer absorbs the shocks causing the air spring to break.





Oil in the air spring

Oil deteriorates the rubber of the air spring. The oil in an air spring is caused by a broken/leaking shock absorber.



NL +31 (0)73 7850 580 DE +49 (0)699 6759106 UK +44 (0)203 3186124 BE +32 (0)258 846 90





Car is not supported by a jack when inflating the air spring

You have to support the car with a jack when you start to inflate the new air spring. Otherwise the air bladder is pulled out of the crimp ring.





Air struts

Bolts have been broken off

This is an installation error whereby the mechanic has overtightened the bolt.





NL +31 (0)73 7850 580 DE +49 (0)699 6759106 UK +44 (0)203 3186124 BE +32 (0)258 846 90



Compressors

AAAA

AA

Discolored sticker and/or a burning smell

If the sticker is yellowish or the compressor smells burned, the compressor has been overheated/burned out. This is usually caused by a leak in the air suspension system.





NL +31 (0)73 7850 580 DE +49 (0)699 6759106 UK +44 (0)203 3186124 BE +32 (0)258 846 90